

Cool Pack (RP606) Instructions

Use the Cool Pack (RP606) with the following DQE products:

- Cooling Vest—Concealable (RP6210)
- Cooling Vest—Zipper Front (RP6211)
- Decon Team Cooling Vests (RP61012)

1. Prior to using, inspect your Cool Pack. The cooling fluid is non-toxic but may cause skin irritation if ruptured. Damaged Cool Packs should not be used. See the included Material Safety Data Sheet (MSDS) for more information.
2. To charge the Cool Pack, place it in ice and water, a refrigerator, or a freezer. It will charge completely in 20-30 minutes. The fluid will turn to a white solid when charged.
3. Place the Cool Pack in the inside pocket of your vest. You will feel an initial sensation of coolness, but your body will quickly adjust to the temperature. As long as there is any solid white material in the pack, it will maintain a 59 degree F temperature and cool your body.
4. A snug cooling vest works best. Use a light t-shirt under the vest, so the vest is as close to the skin as possible.
5. The Cool Pack will last up to 3 hours depending on heat and humidity levels. Check it occasionally during use and recharge in ice and water when possible.